









		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**AG2**	0 to 0.25...12 bar	Gauge, Vacuum	Analogue	0.5 FS	3, 3.3, 5	-40 to +105	Yes	SMD
	**AT7**	0 to 0.25...12 bar	Gauge, Vacuum	Digital	1.5 FS	3, 3.3, 5	-40 to +107	Yes	SMD
	**AD3**	0 to 0.25...12 bar	Gauge, Vacuum, Differential	Analogue	1.5 FS	5	-40 to +125	Yes	SMD
	**AP3 / AG3 Dedicated Low Noise NIBP Sensor :: non invasive blood pressure monitors**	0 to 330...375mmHg	Gauge, Vacuum	Analogue	±2.5mmHg	3, 3.3, 5	-40 to +106	Yes	SMD
	**PHPSU-4502: SCX Compatible**	0 to 10 mbar...7 bar	Differential, Absolute	Unamplified	0.5 FS	12-20	-25 to +85	Yes	THT
	**89**	0 to 1...7 bar	Gauge, Absolute	Digital, Analogue	1.5 FS	3.3, 5	-20 to 85	Yes	THT
	**AG4**	0 to 0.25...12 bar	Gauge, Vacuum	Digital	0.5 FS	3, 3.3, 5	-40 to +107	Yes	SMD
	**AP3 / AG3-X1 / AG3xF:: Replacement for XFPM, XFGM & XFAM series**	0 to 0.25...12 bar	Gauge, Vacuum	Analogue	0.5 FS	3, 3.3, 5	-40 to +105	Yes	SMD


		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**AP2**	0 to 0.25...12 bar	Gauge, Vacuum	Analogue	0.5 FS	3, 3.3, 5	-40 to +125	Yes	THT
	**AL4**	0 to 20...200 mbar	Gauge, Vacuum, Differential	Digital	0.5 FS	3, 3.3, 5	-40 to +85	Yes	SMD
Fujikura	**Fujikura overview**	0 to 0.02...12 bar	Gauge, Vacuum, Differential, Absolute	Analogue, Digital, Unamplified	0.5 FS	3, 3.3, 5	-40 to +125	Yes	SMD, THT
	**52**	0 to 2 mbar...7 bar	Gauge, Vacuum, Differential, Absolute	Digital, Analogue	0.5 FS	3.3, 5	0 to +70	Yes	SMD
	**30DL with parylene coating**	0.3 to 4...16 bar	Absolute	Digital	8cm altitude resolution (RMS)	1.8...3.6	-20 to +85	Yes	SMD
	**PBM210**	0.3 to 1.1...15 bar	Absolute	Digital	8cm altitude resolution (RMS)	1.7...5.5	-40 to +85	Yes	SMD
	**PBM220 with protection gel**	0.3 to 1.1...14 bar	Absolute	Digital	8cm altitude resolution (RMS)	1.7...5.5	-40 to +85	Yes	SMD
	**PBM230 with protection gel**	0.3 to 1.1...16 bar	Absolute	Digital	8cm altitude resolution (RMS)	1.7...5.5	-40 to +85	Yes	SMD





		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**AH3**	0 to 0.25...12 bar	Gauge, Vacuum	Analogue	1.5 FS	3, 3.3, 5	-40 to +125	Yes	THT
	**AP3 low noise sensor with pressure threshold detection**	0 to 0.25...12 bar	Gauge, Vacuum	Analogue	0.5 FS	3, 3.3, 5	-40 to +125	Yes	THT
	**AP4**	0 to 0.25...12 bar	Gauge, Vacuum	Digital	0.5 FS	3, 3.3, 5	-40 to +125	Yes	THT
	**APB2**	0 to 0.25...12 bar	Gauge, Vacuum	Analogue	0.5 FS	3, 3.3, 5	-40 to +125	Yes	THT
	**PHPS-3500**	0 to 1 mbar...7 bar	Gauge, Vacuum, Differential, Absolute	Analogue, Digital	0.5 FS	5	-25 to +85	Yes	THT
	**PHPSU-3500**	0 to 1 mbar...7 bar	Gauge, Vacuum, Differential, Absolute	Unamplified	0.5 FS	5V	-25 to +85	Yes	THT
	**PHPS-7500 wet/wet**	0 to 0.01...10 bar	Differential	Analogue, Digital	0.75 FS	5	-25 to +85	Yes	THT
	**PHPS-8500**	0 to 1 mbar...10 bar	Differential, Absolute	Analogue, Digital	0.5 FS	2.7...5.25V	-40°C to +85°C	Yes	


		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**SPD Series hybrid analogue**	0 to 0.3...100 PSI	Gauge, Absolute, Differential, Single	Analogue	1.8 FS	4.75, 5, 5.25	-40 to +125	Yes	THT
	**SPD Series hybrid digital**	0 to 0.3...100 PSI	Gauge, Absolute, Differential, Single	Digital	1.8 FS	2.7, 5, 5.25	-20 to +125	Yes	THT
	**SPD Series hybrid unamplified**	0 to 15...100 PSI	Gauge, Absolute	Unamplified	+/- 0.3 FS	2.7, 5, 10	-40 to +125	No	SMD
	**SPD Series SIL/DIL analogue**	0 to 100 PSI	Gauge, Absolute	Analogue	0.5 FS and greater	2.7, 5, 5.5	-40 to +125	Yes	THT
	**SPD Series SIL/DIL digital**	0 to 100 PSI	Gauge, Absolute	Digital	1.8 FS	2.7, 5, 5.5	-20 to +85	Yes	THT
	**SPD Series SIL/DIL unamplified**	0 to 100 PSI	Gauge, Absolute	Unamplified	check datasheet	0, 5, 10	-40 to +85	No	THT
	**SPD Series SMD/SOT analogue**	-0.15 to 30 PSI	Gauge, Vacuum, Absolute, Differential	Analogue	1.8 FS	4.75, 5, 5.5	-40 to +125	Yes	SMD
	**SPD Series SMD/SOT unamplified**	-0.3 to 100 PSI	Gauge, Absolute	Unamplified	check datasheet	0, 5, 10	-40 to +125	No	SMD/SOT

		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**SPD Series TO05 analogue**	0 to 30...435 PSI	Absolute	Analogue	1.8 FS	4.75, 5, 5.5	-20 to +100	Yes	THT
	**SPD Series TO05 unamplified**	0 to 290 PSI	Absolute	Unamplified	check datasheet	0, 5, 10	-20 to +85	No	THT
	**Sensor + Flex**	Customized	Customized	Customized	Customized	Customized	Customized	Customized	Customized
	**Sensor + PCB (FR4)**	Customized	Customized	Customized	Customized	Customized	Customized	Customized	Customized
	**ABS5**	0.3 to 1.1...10 bar	Absolute	Digital	0.02 hPa/count	1.8...3.6	-40 to +85	Yes	SMD
	**PLDS-Custom-Made**	Customized	Customized	Customized	Customized	Customized	Customized	Customized	Customized
	**CCD54**	0 to 2.5 mbar...10 bar	Gauge, Vacuum, Differential, Absolute	Analogue, Digital	1.8 FS	3, 5	-20 to +85	Yes	SMD, THT
	**CCD53**	0 to 2.5 mbar...10 bar	Gauge, Vacuum, Differential, Absolute	Analogue, Digital	1.8 FS	3, 5	-20 to +85	Yes	SMD, THT

		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**STX**	0 to 1 mbar...7 bar	Gauge, Vacuum, Differential, Absolute	Analogue, Digital	2.2 FS	3, 5	-20 to +85	Yes	THT
	**FAM**	1 to 0.14...0.48 bar	Absolute	Unamplified	2.5 FS	0...15	-20 to +100	No	SMD
	**FPN**	0 to 0.14...0.48 bar	Gauge, Vacuum	Unamplified	2.5 FS	0...15	0 to +80	No	THT
	**FGN-6**	1 to 0.14...0.48 bar	Gauge, Vacuum	Unamplified	2.5 FS	0...15	0 to +80	No	SMD
	**FPM**	0 to 0.14...10 bar	Gauge, Vacuum	Unamplified	2.5 FS	0...15	-20 to +100	No	THT
	**FGM-3/6**	0 to 0.14...10 bar	Gauge, Vacuum	Unamplified	2.5 FS	0...15	-20 to +100	No	SMD
	**FHM**	0 to 0.14...10 bar	Gauge, Vacuum	Unamplified	2.5 FS	0...15	-20 to +100	No	THT
	**FDM**	0 to 0.14...10 bar	Gauge, Vacuum, Differential	Unamplified	2.5 FS	0...15	-20 to +100	No	SMD

		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**XFPN**	0 to 0.25...2 bar	Gauge, Vacuum	Analogue	5 FS	5	-10 to +80	Yes	THT
	**XFGN-6**	0 to 0.25...2 bar	Gauge, Vacuum	Analogue	5 FS	5	-10 to +80	Yes	SMD
	**XFPM**	0 to 0.25...12 bar	Gauge, Vacuum, Absolute	Analogue	2.5 FS	5	-40 to +125	Yes	THT
	**XFGM-3/6**	0 to 0.25...12 bar	Gauge, Vacuum	Analogue	2.5 FS	5	-40 to +125	Yes	SMD
	**XFHM**	0 to 0.25...12 bar	Gauge, Vacuum	Analogue	2.5 FS	5	-40 to +125	Yes	THT
	**XFDM**	0 to 0.25...12 bar	Gauge, Vacuum, Differential	Analogue	2.5 FS	5	-40 to +125	Yes	SMD
	**XFAM**	150 to 1150 mbar	Absolute	Analogue	2.5 FS	5	-40 to +125	Yes	SMD
	**MS5803-01BA**	10...1300 mbar	Absolute	Digital	1 FS	1.8...3.6	-40 to +85	Yes	SMD

		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**1451**	0 to 0.35...30 bar	Gauge, Vacuum, Absolute	Unamplified	0.5 FS	0...12	-40 to +125	No	SMD
	**1471**	0 to 0.35...30 bar	Gauge, Vacuum, Absolute	Unamplified	0.5 FS	0...12	-40 to +125	No	SMD
	**MIS-2500**	0 to 0.07...10 bar	Gauge, Vacuum	Analogue	1.3 FS	3...5	-40 to +85	Yes	THT
	**MIS-3600**	0 to 0.035...2 bar	Gauge, Vacuum, Differential	Digital	1 FS	2...3.6	-40 to +85	Yes	SMD
	**SLP35**	0 to 0.02...7 bar	Gauge, Vacuum, Differential	Analogue, Digital	1.8 FS	2.7...5.5	-20 to +85	Yes	SMD
	**MS8607**	10 to 2000 mbar	Absolute	Digital	2 FS	1.5...3.6	-40 to +85	Yes	SMD
	**MS5611**	10 to 1200 mbar	Absolute	Digital	2 FS	1.8...3.6	-40 to +85	Yes	SMD
	**IPPS-015**	0.3 to 1.1 bar	Absolute	Digital	1 FS	2.0...3.6	-40 to +85	Yes	SMD

		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**HPSA1000**	0 to 0.05...7 bar	Gauge, Absolute	Unamplified	0.5 FS	0...10	-25 to +85	No	SMD
	**HPSD1000**	0 to 0.05...7 bar	Gauge, Vacuum, Absolute	Analogue, Digital	1 FS	5	-25 to +85	Yes	SMD
	**HPSAV3000**	0 to 0.01...7 bar	Gauge, Vacuum, Differential, Absolute	Unamplified	1 FS	0...20	-25 to +85	Yes	THT
	**HPSD4000**	0 to 0.01...7 bar	Gauge, Vacuum, Differential, Absolute	Analogue, Digital	1 FS	5	-25 to +85	Yes	THT
	**13**	0 to 0.07...17 bar	Gauge, Vacuum, Absolute	Unamplified	0.5 FS	0...12	-40 to +125	Yes	THT
	**17**	0 to 1...17 bar	Gauge, Vacuum, Absolute	Unamplified	0.5 FS	0...12	-40 to +125	Yes	THT
	**23**	0 to 0.07...17 bar	Gauge, Differential	Unamplified	0.5 FS	0...12	-40 to +125	Yes	THT
	**27**	0 to 1...17 bar	Gauge, Differential	Unamplified	0.5 FS	0...12	-40 to +125	Yes	THT

		Messbereich	Druckart	Ausgangstyp	Genauigkeit [%]	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart
	**33**	0 to 0.07...17 bar	Gauge, Differential	Unamplified	0.5 FS	0...12	-40 to +125	Yes	THT
	**37**	0 to 1...17 bar	Gauge, Differential	Unamplified	0.5 FS	0...12	-40 to +125	Yes	THT
	**43**	0 to 0.07...17 bar	Gauge, Vacuum, Absolute	Unamplified	0.5 FS	0...12	-40 to +125	Yes	THT
	**47**	0 to 1...17 bar	Gauge, Vacuum, Absolute	Unamplified	0.5 FS	0...12	-40 to +125	Yes	THT

Angst+Pfister
Sensors and Power

We are here for you. Addresses and Contacts.

Headquarter Switzerland:

Angst+Pfister Sensors and Power AG
Thurgauerstrasse 66
CH-8050 Zurich
Phone +41 44 877 35 00
sensorsandpower@angst-pfister.com

Office Germany:

Angst+Pfister Sensors and Power Deutschland GmbH
Edisonstraße 16
D-85716 Unterschleißheim
Phone +49 89 374 288 87 00
sensorsandpower.de@angst-pfister.com

Scan here and get an overview of personal contacts!

sensorsandpower.angst-pfister.com