
		Produkttyp	Ausgangssignal
	**SHTM high-temperature humidity transmitter**	Gas sensor transmitter	4-20 mA
	**FCX-OHSLIGHT high-temperature humidity/oxygen transmitter**	Gas sensor transmitter	4-20 mA
	**PHTM high-temperature humidity and temperature data logger**	Humidity and temperature data logger	data logging
	**FCX-OHS high-temperature humidity transmitter - discontinued (please see SHTM)**	Gas sensor transmitter	4-20 mA

Angst+Pfister
Sensors and Power

We are here for you. Addresses and Contacts.

Headquarter Switzerland:

Angst+Pfister Sensors and Power AG
Thurgauerstrasse 66
CH-8050 Zurich
Phone +41 44 877 35 00
sensorsandpower@angst-pfister.com

Office Germany:

Angst+Pfister Sensors and Power Deutschland GmbH
Edisonstraße 16
D-85716 Unterschleißheim
Phone +49 89 374 288 87 00
sensorsandpower.de@angst-pfister.com

Scan here and get an overview of personal contacts!

sensorsandpower.angst-pfister.com