


		Winkel [°]	Quecksilberfrei	Spannung
	**AG1260-0**	60	Yes	60 VAC
	**AG3011-0**	15	Yes	24 VDC
	**AG3011-70**	20	Yes	24 VDC
	**AG3011-90**	10	Yes	24 VDC
	**AU1360-1**	60	Yes	60 VDC/AC
	**AU2100-0**	15	Yes	50 VAC
	**CM100-0**	10	No	240 VAC
	**CM1000-0**	10	No	240 VAC

		Winkel [°]	Quecksilberfrei	Spannung
	**CM1300-0**	10	No	240 VAC
	**CM1320-0**	10	No	240 VAC
	**CM1350-1**	50	No	240 VAC
	**CM1360-0**	30	No	120 VAC
	**CM1365-0**	60	No	120 VAC
	**CM1370**	60	No	240 VAC
	**CM1415-1**	15	No	240 VAC
	**CM1445**	45	No	240 VAC

		Winkel [°]	Quecksilberfrei	Spannung
	**CM1490**	45	No	240 VAC
	**CM1600-0**	2	No	240 VAC
	**CM1702-1**	2	No	240 VAC
	**CM1706-1**	6	No	240 VAC
	**CM1715-1**	15	No	240 VAC
	**CM1800-1**	2	No	120 VAC
	**CM200-70**	10	No	240 VAC
	**CM225-0**	25	Yes	240 VAC

		Winkel [°]	Quecksilberfrei	Spannung
	**CM265-0**	65	Yes	240 VAC
	**CW1300**	15	Yes	60 VDC/AC
	**CW1430-0**	5	Yes	60 VAC
	**CW1600**	15	Yes	60 VDC/AC
	**CW1620-3**	10	Yes	60 VAC
	**CW1725**	30	Yes	60 VAC
	**CW1740**	100	Yes	60 VAC
	**CW1745-0**	45	Yes	60 VAC

		Winkel [°]	Quecksilberfrei	Spannung
	**CW60A/30**	15	Yes	60 VAC
	**CW60S/15**	15	Yes	60 VAC
	**S1016**	15	Yes	120 VAC
	**S1039**	15	Yes	60 VAC
	**S1234**	35	Yes	60 VAC
	**S1261**	60	Yes	60 VDC/AC
	**BS79**		Yes	24 VDC
	**BS79R**		Yes	24 VDC

		Winkel [°]	Quecksilberfrei	Spannung
	**ASLS**		Yes	24 VDC
	**AS1303-0**		Yes	24 VDC

Angst+Pfister
Sensors and Power

We are here for you. Addresses and Contacts.

Headquarter Switzerland:

Angst+Pfister Sensors and Power AG
Thurgauerstrasse 66
CH-8050 Zurich
Phone +41 44 877 35 00
sensorsandpower@angst-pfister.com

Office Germany:

Angst+Pfister Sensors and Power Deutschland GmbH
Edisonstraße 16
D-85716 Unterschleißheim
Phone +49 89 374 288 87 00
sensorsandpower.de@angst-pfister.com

Scan here and get an overview of personal contacts!

sensorsandpower.angst-pfister.com