






		Messbereich [N]	Ausgangssignal	Genauigkeit [$\pm$ % FS] max.	Speisespannung [VDC]
	LoadSensor	Customized	Customized	Customized	Customized
	MilliNewton	0.4, 1.0, 2.0	0.50...3.50 VDC (ratiometric output)	1	5
	CentoNewton	10, 20, 40, 100, 200	0.50...3.50 VDC (ratiometric output)	10	5
	FX29	50, 125, 250, 500, 1000	20 mV/V, Amplified (0.5V-4.5V), I2C	0.8	2.7...6
	FC22	45, 110, 225, 450	100mV, 0.5 to 4.5VDC	1	5
	FC23	1100, 2250, 4500, 9000	100mV, 0.5 to 4.5VDC	1	5
	FS20	7, 14	1.0 to 4.0VDC	1	5
	FS1901	5, 10, 20, 30	20 mV/V (ratiometric to excitation voltage)	1	2...10



FX1901

Messbereich [N]	Ausgangssignal	Genauigkeit [± % FS] max.	Speisespannung [VDC]
45, 110, 225, 450	20 mV/V (ratiometric to excitation voltage)	1	5

We are here for you. Addresses and Contacts.

Headquarter Switzerland:

Angst+Pfister Sensors and Power AG
Thurgauerstrasse 66
CH-8050 Zurich
Phone +41 44 877 35 00
sensorsandpower@angst-pfister.com

Office Germany:

Angst+Pfister Sensors and Power Deutschland GmbH
Edisonstraße 16
D-85716 Unterschleißheim
Phone +49 89 374 288 87 00
sensorsandpower.de@angst-pfister.com

Scan here and get an overview of personal contacts!



sensorsandpower.angst-pfister.com